

Work Order ID 145367

Thursday, May 05, 2016 3:19:14 PM

145367

Page 1

Item ID: D206-628-022 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Heli-Access-Step™ RH - High Gear 206L/L1/L3/L4
 Start Date: 5/24/2016 Start Qty: 2.00 ***2*** Cust Item ID:
 Required Date: 5/28/2016 Req'd Qty: 2.00 ***2*** Customer:
 Reference:

Approvals: Process Plan: gem Date: 16/05/05 Tooling: _____ Date: _____
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____
 Run Start ***NR1***
 Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
N/A	Rev N/A								
100	Document Control	0.00	DAS 6 9-89						MCS 16-05-31
100	DOCUMENT CONTROL								2
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy blue file and type labels as per PPP D206-628-022 CHG 003								
									JUN 02 2016
110	Pick Kit	0.00							
110									
Packaging	Memo	0.00	DAS 6 9-89						MAY 31 2016
Packaging									2
									DAS 28 9-89
120	QC4- 100% Inspect kits for completeness	0.00							
120									
QC	Memo	0.06							JUN 03 2016
Quality Control									

B145961 {X3R4}

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY					
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____						
Misidentified ☐	Past Due ☐							

Work Order ID 145367

Thursday, May 05, 2016 3:19:14 PM

145367

Page 2

Item ID: D206-628-022

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Heli-Access-Step™ RH - High Gear 206L/L1/L3/L4

Start Date: 5/24/2016 Start Qty: 2.00 ***2***

Cust Item ID:

Required Date: 5/28/2016 Req'd Qty: 2.00 ***2***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	Packaging	0.00							
130									
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D206-628-022 Location : FG081								
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.20							
Quality Control									

BAS
27
9-29
JUN 03 2016

MCS JUN 03 2016

MCS JUN 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : _____					

Picklist Print

Thursday, May 05, 2016 3:19:17 PM

Page 1

Work Order ID: 145367

145367

Parent Item: D206-628-022

D206-628-022

Parent Item Name: Heli-Access-Step™ RH - High Gear 206L/L1/L3/L4

Start Date: 5/24/2016

Required Date: 5/28/2016

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev:D as per ECN 766 JLM
IPP Rev:E as per ecn 1118 DD verified by:EC IPP Rev:F
10.08.13 CHG QTY OF RUBBER DD verf by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2724-042		Manufactured	No				Each	0.0000	1	2			DAS 28 9-89
D2724-042									**				
206L Step Assembly, RH27													
NAS1149D0463J		Purchased	No				Each	1,420.000	12	24			
NAS1149D0463.J									**				
WASHER													

DAS
27
9-89

Location	Loc Qty	Loc Code
GA	328	
M132035	21	
M134508	307	
ST260a	998	
M134634	998	
ST263	94	
M134508	94	

DAS
28
9-89

AN4-14A

Purchased No

120 Each 355.0000 4 8

AN4-14A

Bolt

**

Location	Loc Qty	Loc Code
FG	5	
122141	5	
over003	250	
M134508	100	
M134573	150	
ST344	100	
M133998	100	

DAS
27
9-89

DAS
6
9-89

MAY 31 2016

DAS
28
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :	MRB (QS1042) Approval		
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Thursday, May 05, 2016 3:19:17 PM

Page 2

Work Order ID: 145367

145367

Parent Item: D206-628-022

D206-628-022

Parent Item Name: Heli-Access-Step™ RH - High Gear 206L/L1/L3/L4

Start Date: 5/24/2016

Required Date: 5/28/2016

Start Qty: 2.00

Required Qty: 2.00

AN4-15A

Purchased

No

120

Each

320.0000

8

16

AN4-15A

Bolt

**

DAS 28
6 9-89
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

34

120449

34

over003

200

m134606

200

ST343

86

m134606

86

D2731-7

Manufactured

No

120

Each

46.0000

4

8

D2731-7

Mounting Lug

**

DAS 28
6 9-89
9-89

Location

Loc Qty

Loc Code

ST520

22

135953

22

ST532A

24

141431

24

D2732-030

Manufactured

No

120

Each

109.0000

8

16

D2732-030

Rubber Cushion - 3"

**

DAS 28
6 9-89
9-89

Location

Loc Qty

Loc Code

FG

10

135594

10

ST410

99

144517

79

144999

20

DAS
27
9-89

MAY 31 2016

Thursday, May 05, 2016 3:19:18 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Thursday, May 05, 2016 3:19:18 PM

Page 3

Work Order ID: 145367

145367

Parent Item: D206-628-022

D206-628-022

Parent Item Name: Heli-Access-Step™ RH - High Gear 206L/L1/L3/L4

Start Date: 5/24/2016

Required Date: 5/28/2016

Start Qty: 2.00

Required Qty: 2.00

D3394-043

Manufactured No

120

Each

78.0000

4 8

D3394-043

Lug

**

DAS

6

9-89

DAS

28

9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST528

54

134677

2

135954

12

137643

20

138239

20

ST532A

24

140957

24

MS21042L4

Purchased

No

120

Each

1,670.000

12

24

MS21042L4

Locknut

**

DAS

6

9-89

DAS

28

9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

279

m133769

279

OVER007

500

m134676

500

ST303

794

m134606

794

ST305

97

m130922

97

~~134754~~
~~13467~~

24

MAY 31 2016

Thursday, May 05, 2016 3:19:18 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
OTHER : _____									

REFERENCE ONLY

DART AEROSPACE USA, INC.

IIN-D206-628

Page 17 of 19

5.1 D206-628-011/-012/-021/-022/-031/-032 REGULAR DART HELI-ACCESS- STEPS™ PARTS LIST

Qty -011	Qty -012	Qty -021	Qty -022	Qty -031	Qty -032	Part Number	Description
X						D206-628-011	206 A/B STEP INSTALLATION LH
	X					D206-628-012	206 A/B STEP INSTALLATION RH
		X				D206-628-021	206 L/L1/L3/L4 STEP INSTALLATION LH
			X			D206-628-022	206 L/L1/L3/L4 STEP INSTALLATION RH
				X		D206-628-031	407 STEP INSTALLATION LH
					X	D206-628-032	407 STEP INSTALLATION RH
1						D2721-041	STEP ASSEMBLY LH
	1					D2721-042	STEP ASSEMBLY RH
		1		1		D2724-041	STEP ASSEMBLY LH
			1		1	D2724-042	STEP ASSEMBLY RH
				4	4	D2731-3	MOUNTING LUG
4	4	4	4			D2731-7	MOUNTING LUG
8	8	8	8	8	8	D2732-030	RUBBER CUSHION
				4	4	D3394-041	MOUNTING LUG
				4	4	*D3394-1	*MOUNTING LUG
				8	8	*MS35489-93	*GROMMET
4	4	4	4			D3394-043	MOUNTING LUG
4	4	4	4			*D3394-3	*MOUNTING LUG
8	8	8	8			*MS35489-93	*GROMMET
4	4			4	4	AN4-13A	BOLT
4	4	4	4	4	4	AN4-14A	BOLT
4	4	8	8	4	4	AN4-15A	BOLT
12	12	12	12	12	12	NAS1149D0463J	WASHER (AN960JD416)
12	12	12	12	12	12	MS21042L4	NUT (OR MS21042-4)

*DENOTES THAT PART IS INCLUDED IN ASSEMBLY ABOVE

• COPYRIGHT © 2005 BY DART AEROSPACE USA, INC. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: G
Date: 11.02.25